



Mercedes-Benz

## service information

**TO:** OUR MERCEDES-BENZ PASSENGER CAR DEALERS


**DATE:** May 1992

**REF. NO.** 61/4

**SUBJECT:** MODEL 124.036  
ENGINE COMPARTMENT PANELING

On some vehicles the lower engine compartment panel was incorrectly installed during production. The panel projects into the sides of the wheelhouse liners instead covering them from below.

During the next maintenance requiring the removal of the lower engine compartment panel (1), make certain that you reinstall it in a such way that it will cover the left and right side wheelhouse liner (2) as illustrated. To do so, install the sheet metal clip nuts of the engine compartment panel on the wheelhouse liners.



- 1 Engine compartment panel
- 2 Wheelhouse liner

### Effective Serial Number Range

Model	From Chassis End Number	To Chassis End Number
124.036	B355394	B608656