



Mercedes-Benz

**star bulletin**



Date: June 2002  
Order No.: S-B-72.00/01  
Supersedes: S-SI-MBNA-72/10 dated January 1994  
Group: 72

**SUBJECT: ALL MODELS  
ALL OUTER DOOR PANELS BEING REPLACED BY DOOR SHELL**

Effective immediately for all models, the outer door panels are no longer available. In case of repairs in which the outer panel could previously have been replaced (as noted in the Electronic Parts Catalog [EPIC]), a complete door must be used.

The installation and refinishing of the outer panel, is very time consuming and not cost effective when compared to the installation of the complete door.

This bulletin has been created and maintained in accordance with MBUSA-SLP 5.1, Document and Data Control, and MBUSA-SLP 16.1, Control of Quality Records.